



**HYCOL DIVISION • THE DEXTER CORPORATION**  
P. O. BOX 312, PITTSBURG, CALIF. 94565 415-687-4201

DPM 894

Adhesive Epoxy  
Detached, not replaced

May 12, 1977

— NOT HAZ.

— HAZ.

Douglas Aircraft Company  
3855 Lakewood Boulevard  
Long Beach, California 90846

Attention: Mr. J. Veneroso, Department CI-726 (52-11)  
Materials Handling and Packaging Engineering

— Reference: CI-726-124

Gentlemen:

Regarding your April 29, 1977 inquiry, we are enclosing information on the following products:

EA 951 and EA 951S — QPL 2103  
EA 8 (formerly VIII) and Curing Agent A — DPM 894  
✓ EA 6 and Curing Agent A — DPM 5655-1  
✓ EA 934 — DPM 5535-1  
✓ EA 956 — DPM 5535-1  
EA 9311 — " 5754  
EA 9308 — 7th DPM (10/2/77)

All other items on your list are products of the Hysol plant in Industry, Calif.  
A copy of your request has been forwarded to them for reply.

OSHA Material Safety Data Sheets are enclosed for all of the aforementioned EA adhesives. Flash point information is included in these OSHA forms.  
The following are classified as "non-restricted articles":

EA 951 and EA 951S — QPL 2103  
✓ EA 934 — DPM 5535-1  
✓ EA 956 — DPM 5535-1  
EA 9311 — " 5754

Curing Agent A, which is the catalyst (Part B) for both EA 6 and EA 8 is a "Corrosive Liquid N.O.S." (DOT Shipping Name) and a "Corrosive Material" (DOT Hazard Classification). IATA Article #522.

EA 9308, Part B is a "Poisonous Liquid N.O.S. (Epoxy Hardener)" and "Poison Class B" — the DOT Shipping Name and Hazard Classification, respectively. IATA Article #1438.

DOUGLAS AIRCRAFT COMPANY

2.

We trust this information will be useful to you when reshipping Hysol materials.

Very truly yours,

  
R. M. Seppala  
Manager Marketing Services

cc: J. S. Hutcheon  
Hysol Division  
The Dexter Corporation  
Industry, California

Enclosures

RMS:mem